

Status Anschaltung DECT 3 / 32 an Fremdsysteme

Hersteller	Anlage	SW	Art	Protokoll	DECT 3	DECT 32	Ver.	Status	Bemerkung
Auerswald	ETS 4308 i	1.1 L	PzMP	DSS1	X		DC	o.k.	
Ackermann	Euracom 181	Vers. 2.03	PzMP	DSS1	X		CT	o.k.	
Agfeo	AS 40	1.0 Q	PzMP	DSS1	X		DC	o.k.	
Ascom	BCS 8	3.0	PzMP	DSS1	X		B	o.k.	
	BCS 64	i3plus	PzMP	DSS1	X	X	B	o.k.	
Bosch	Integral 33x	E 03.2	PzMP	DSS1		X	B	o.k.	
		E 03.2	PzP	QSIG		X	B	o.k.	
	Integral i3	6.100 D	PzMP	DSS1	X	X	B	n.m.	
DeTeWe	Content 840	PTS 200.033.18	PzMP	1TR6		X	CT	o.k.	
	Varix 200								
Elmeg	C88 M	A 1.0	PzMP	DSS1	X		CT	o.k.	
	C48 M	A 1.0	PzMP	DSS1	X		CT	o.k.	
	128 E							n.m.	
Ericsson	Business Phone	Release 9	PzMP	DSS1		X	B	n.m.	
		Release 9	PzP	QSIG		X	B	o.k.	
		Release 9	S2M	QSIG		X	B	o.k.	
	MD 110								
Hagenuk	DCS 50	SW 2.7	PzMP	DSS1	X	X	CT	o.k.	
	ICS 100	AF 3.0	PzMP	1TR6	X	X	CT	o.k.	
		AG 1.6	PzMP	DSS1	X	X	B	o.k.	
Kapsch	MidiStar	A 02 V04 3.01.11	PzMP	DSS1	X		CT	o.k.	
Lucent	EuroGeneris	V 600	PzMP	DSS1	X	X		o.k.	
	Definity	G3V6i 02.0.120.5	S2M	QSIG		X	B	o.k.	
Matra	MC 6501	8.6 T1	PzMP	DSS1		X	B	o.k.	
	MC 6504								

Status Anschaltung DECT 3 / 32 an Fremdsysteme

Hersteller	Anlage	SW	Art	Protokoll	DECT 3	DECT 32	Ver.	Status	Bemerkung
Nitsuko	32 i	Vers. 21	PzMP	DSS1	X	X	B	n.m.	Zeitweises blockieren der S0-Ports der HA.
NT	Meridian 1	Rel. 22.16	PzMP	DSS1		X	B	o.k.	Geringer Leistungsumfang nutzbar.
		Rel. 22.16	PzP	QSIG		X	B	o.k.	
		Rel. 22.16	S2M	QSIG		X	B	o.k.	
Panasonic	KX-TD 1232	SW P061 H	PzMP	DSS1	X		B	o.k.	
Philips	Sopho S	CPU 805.27 A	PzMP	DSS1		X	DC	o.k.	Nur 2 MSN pro S0-Bus möglich !
		CPU 805.27 A	PzP	QSIG		X	B	o.k.	
		CPU 805.27 A	S2M	QSIG		X	B	n.m	Protokollfehler bei kommenden Verbindungen.
	iMAGINATION	205.8	PzMP	DSS1	X	X	DC	o.k.	
SEL	4200 CM	CD 21.1/14.9	PzMP	DSS1	X	X	DC	o.k.	Nur 3 MSN pro S0-Bus möglich !
	4200 E	3.0 /300/39.9	PzMP	DSS1	X	X	DC	o.k.	Nur 3 MSN pro S0-Bus möglich !
	4400								
	5630								
Siemens	HICOM 150	APS 104 Tool 19	PzMP	DSS1	X	X	B	o.k.	
	HICOM 200								
	HICOM 300	Vers. 3.4-07	PzMP	DSS1		X	DC	o.k.	
		Vers. 3.4-07	PzP	QSIG		X	B	o.k.	Kein Basic call ! Nur nach ECMA 2 möglich.
	HICOM 118								
	HICOM 120								
Telekom	Octopus 180 i	ZST 3 SW 9.0	PzMP	DSS1		X	DC	o.k.	
		ZST 3 SW 9.0	PzMP	1TR 6		X	DC	o.k.	
	Octopus E 300	Vers. 6.0/01	PzMP	DSS1		X	CT	o.k.	
	Octopus 8818	Vers. 5.4/01	PzMP	DSS1	X	X	CT	o.k.	
		Vers. 5.4/01	PzMP	1TR 6	X	X	CT	o.k.	